



CITY OF SAINT PAUL

Code Compliance Report

January 31, 2025

*** * This Report must be Posted
on the Job Site * ***

925 Magnolia Avenue E Llc
5544 Harriet Ave
Minneapolis MN 55419-1830

Re: 925 Magnolia Ave E
File#: 10 514366 VB3

Dear Property Owner:

The following is the Code Compliance report you requested on October 24, 2024.

Please be advised that this report is accurate and correct as of the date January 31, 2025. All deficiencies identified by the City after this date must also be corrected and all codes and ordinances must be complied with. This report is valid for 365 days from January 31, 2025. This report may be used in lieu of a Truth in Housing Report required in St Paul Legislative Code 189. This building must be properly secured and the property maintained at all times.

In order to sell or reoccupy this property the following deficiencies must be corrected. A Legislative Code exemption (Chapter 33.03(f)) allows a Category 2 Vacant Building to be sold "as is" providing the buyer, prior to closing, completes an approval process. For further information, call Robert Humphrey at 651-266-9123.

Please note that permits cannot be issued online. Permits must be applied for in person, via fax or mail.

ZONING

1. This property is in a(n) H1 zoning district.
2. This property was inspected as a Duplex.

BUILDING Inspector: Clint Zane

Phone: 651-266-9029

1. Insure basement cellar floor is even, is cleanable, and all holes are filled. SPLC

- 34.10 (1)
2. Prepare and paint interior and exterior as necessary. Observe necessary abatement procedures (EPA, MPCA and St. Paul Legislative Code, Chapter 34 for additional information) if lead base paint is present. SPLC 34.33 (1)
 3. Provide fire block construction as necessary and seal chases in basement ceiling. MNRC Ch 1309 Sect. 602.8
 4. Where wall and ceiling covering is removed install full thickness or code-specified insulation. MN Energy Code Ch. 1322.1101 (except. 4)
 5. Install Smoke Detectors/Carbon Monoxide Detectors per MN Conservation Code and the MN Dept. of Labor and Industry: Install per code where feasible. MNRC Ch 1309 Sect 313.2.1
 6. Repair siding, soffit, fascia, trim, etc. as necessary. SPLC 34.09 (1)
 7. Install 20 minute fire rated doors, with self closing device, between common areas and individual units. All penetrations required to have property intumescent device or caulk (per current building codes). MNRC Ch 1309 Sect. 317
 8. Maintain one hour fire separation between dwelling units and between units and common areas. MNRC Ch 1309 Sect. 317
 9. Install handrails (34 inches - 38 inches above each nosing) and guardrails (36 inch minimum) at all stairways, and return hand rail ends into a newel post or wall per attachment. MNRC Ch 1309 Sect. 311 & 312
 10. Repair or Replace any deteriorated window sash, broken glass, sash holders, re-putty, etc as necessary. SPLC 34.09 (3)
 11. Provide complete storms and screens, in good repair for all door and window openings. SPLC 34.09 (3e)
 12. Provide functional hardware at all doors and windows. SPLC 34.09 (3f)
 13. Install floor covering in bathroom and kitchen that is impervious to water. SPLC 34.10 (4)
 14. Repair walls, ceiling and floors throughout, as necessary. SPLC 34.34 (6)
 15. A building permit is required to correct the above deficiencies. All work is to be done in a workmanship like manner. SPLC 33.03 (a)

ELECTRICAL Inspector: Dan Moynihan

Phone: 651-266-9036

1. 2nd Floor -SPLC 58 2020 - Install hard-wired smoke detector as specified in Chapter 58 of the Saint Paul Legislative Code, and other smoke detectors and carbon monoxide detectors as required by the Minnesota State Building Code.
2. Basement -NEC 250 - Properly install the electrical service grounding conductor to the metallic water piping system.
3. Basement -NEC 408.4 2020 - Provide a complete circuit directory at service panel indicating location and use of all circuits. Article 408.4, NEC
4. Basement -NEC 240.4 2020 - Verify that circuit breaker amperage matches wire size in panel. Replace improperly sized overcurrent devices. Article 240.4, NEC
5. Basement -NEC 110.12(A) 2020 - Close openings in service panel/junction boxes with knockout seals, breaker blanks, proper cable clamps, and/or

junction box covers. Article 110.12 (A), NEC

6. Throughout -NEC 406.4(D) 2020 - Check all receptacles for proper polarity (including 2-prong) and verify ground on 3-prong receptacles. Ensure all GFCI receptacles are functioning properly. Rewire and/or replace receptacles that are improperly wired or not functioning properly. Article 406.4(D), NEC
7. Throughout -Complete electrical wiring throughout that previous contractors started to current 2023 NEC.
8. All electrical work must be done by a Minnesota-licensed electrical contractor under an electrical permit.

PLUMBING Inspector: Paul Zellmer

Phone: 651-266-9048

1. Basement -Water Heater -(MPC 507.5) Correct the pressure and temperature relief valve discharge.
2. Basement -Water Heater -(MPC 501)Install the water piping for the water heater to code.
3. Basement -Water Heater -(MPC .0100 Q)The water heater must be fired and in service.
4. Basement -Water Piping -(MPC .0100 P & Q) Provide water piping to all fixtures and appliances.
5. Bathroom -Plumbing - General -(MN Rules Chapter 1300.0120) Obtain permits and provide tests/inspections for any plumbing performed without permits.
6. First Floor -Lavatory -(MPC 301.1) Repair/replace the fixture that is missing, broken or has parts missing.
7. First Floor -Sink -(MPC 301.1) Repair/replace the fixture that is missing, broken or has parts missing.
8. First Floor -Toilet Facilities -(MPC 301.1) Repair/replace the fixture that is missing, broken or has parts missing.
9. First Floor -Tub and Shower -(MPC 301.1) Repair/replace the fixture that is missing, broken or has parts missing.
10. Second Floor -Lavatory -(MPC 301.1) Repair/replace the fixture that is missing, broken or has parts missing.
11. Second Floor -Sink -(MPC 301.1) Repair/replace the fixture that is missing, broken or has parts missing.
12. Second Floor -Toilet Facilities -(MPC 301.1) Repair/replace the fixture that is missing, broken or has parts missing.
13. Second Floor -Tub and Shower -(MPC 301.1) Repair/replace the fixture that is missing, broken or has parts missing.
14. All the above corrections to waste, vent, water, and gas piping shall be per the Minnesota Plumbing Code Chapter 4714, Minnesota Rules Chapter 326, 4716, 1300, the Minnesota Mechanical Code, the Minnesota Fuel Gas Code, and Saint Paul Regional Water Services Water Code. All plumbing must be done by a plumbing contractor licensed in the State of Minnesota and the City of St. Paul by a plumber licensed in the State of Minnesota who also possess a City of Saint Paul Competency Card and after obtaining an approved City of Saint Paul Plumbing Permit.

Heating Inspector: Aaron Havlicek

Phone: 651-266-9043

1. Per MFGC 2020 409.1.4 - Install approved lever handle manual building shutoff gas valve in an accessible location ahead of the first branch tee. The main shutoff valve shall be installed in the first available location inside the building 5 feet or less above floor.
2. SPLC 34.11 (6) - Clean and Orsat test furnace/boiler burner. Check all controls for proper operation. Check furnace/boiler heat exchanger for leak; provide documentation from a licensed contractor that the heating unit is safe.
3. Per MFGC 2020 614 - Vent clothes dryer to code. Provide approved piping and valve.
4. Per MFGC 2020 407.2 - Provide support for gas lines to code.
5. Per MMC 2020 1346.0104 - Plug, cap and/or remove all disconnected gas lines, non-conforming gas lines and unapproved valves.
6. Per MMC 2020 1346.0103 - Provide all supply and return ducts for warm air heating system must be clean before final approval for occupancy. Documentation is required from a licensed duct-cleaning contractor that the duct system has been cleaned.
7. Per MMC 2020 1346.0104 - Repair and/or replace heating registers as necessary.
8. SPLC 34.11 Provide heat in every habitable room.
9. Per MMC 2020 307 - Run condensate drain from A/C unit coil in basement to an approved location and secure as needed.
10. Per MMC 2020 1300.0120 - Mechanical permits are required for the above work.
11. Per MMC 2020 601.5 - Provide a means of returning air from every habitable room to the furnace. Return air shall not be taken from closets, bathrooms, toilet rooms, kitchen, or mechanical rooms.
12. Per MMC 2020 1346.0103 - Verify that A/C system is operable, if not, repair, replace or remove and seal all openings.
13. Per MRC 2020 R303.3 - Provide a window in the bathrooms with an aggregate glazing area of not less than 3 square feet, one-half of which must be openable or provide exhaust system vented to outside. A mechanical ventilation permit is required if an exhaust system is installed.

Notes:

1. See attachment for permit requirements and appeals procedure.
2. Roof, sidewalks, etc. snow covered and could not be inspected. All must meet appropriate codes when completed.

Re: 925 Magnolia Ave E
January 31, 2025
Page 5

This is a registered vacant building. In order to sell or reoccupy this building, all deficiencies listed on this code compliance report must be corrected in accordance with the Minimum Housing Standards of the St. Paul Legislative Code (Chapter 34) and all required permits must receive final approval within six (6) months of the date of this report. One (1) six-month time extension may be requested by the owner and will be considered if it can be shown that the code compliance work is proceeding and is more than fifty (50) percent complete in accordance with Legislative Code Section 33.03(f).

You may file an appeal to this notice by contacting the City Clerk's Office at 651-266-8688. Any appeal must be made in writing within 10 days of this notice. (You must submit a copy of this notice when you appeal, and pay a filing fee.)

If you have any questions regarding this inspection report, please contact Clint Zane between 7:30 - 9:00 AM at 651-266-9029 or leave a voice mail message.

Sincerely,

Clint Zane
Code Compliance Officer
Department of Safety and Inspections
City of Saint Paul
375 Jackson Street, Suite 300
Saint Paul MN 55101
Phone: 651-266-9029
Email: Clint.Zane@ci.stpaul.mn.us

Attachments