

**WORK PLAN - BREAKDOWN COST OF REHABILITATION**

(To be done in accordance with the Code Compliance Inspection Report)

Address: 887 Charles Ave

| WEEK OF | TASKS         | CONTRACTOR       | Supplies/Materials on hand (if any) | Needed Supplies/Materials | Owner/Developer Labor | Value of Cost |
|---------|---------------|------------------|-------------------------------------|---------------------------|-----------------------|---------------|
|         | Plumbing      | Kelly Plumbing   |                                     |                           |                       | 7395          |
|         | mechanical    | Baerlin Heating  |                                     |                           |                       | 8375          |
|         | Electrical    | Elofson Electric |                                     |                           |                       | 4500          |
|         | DUCT cleaning | KMS              |                                     |                           |                       | 488.51        |
|         | BUILDING      | Kyle Runbeck     |                                     |                           |                       | 3291.59       |
|         |               |                  |                                     |                           |                       |               |
|         |               |                  |                                     |                           |                       |               |
|         |               |                  |                                     |                           |                       |               |
|         |               |                  |                                     |                           |                       |               |
|         |               |                  |                                     |                           |                       |               |
|         |               |                  |                                     |                           |                       |               |
|         |               |                  |                                     |                           |                       |               |
|         |               |                  |                                     |                           |                       |               |
|         |               |                  |                                     |                           |                       |               |
|         |               |                  |                                     |                           |                       |               |
|         |               |                  |                                     |                           |                       |               |
|         |               |                  |                                     |                           |                       |               |
|         |               |                  |                                     |                           |                       |               |
|         |               |                  |                                     |                           |                       |               |
|         |               |                  |                                     |                           |                       |               |
|         |               |                  |                                     |                           |                       |               |
|         |               |                  |                                     |                           |                       |               |
|         |               |                  |                                     |                           |                       |               |
|         |               |                  |                                     |                           |                       |               |
|         |               |                  |                                     |                           |                       |               |
|         |               |                  |                                     |                           |                       |               |
|         |               |                  |                                     |                           |                       |               |
|         |               |                  |                                     |                           |                       |               |
|         |               |                  |                                     |                           |                       |               |
|         |               |                  |                                     |                           |                       |               |

Total Project Cost: \$ 24000

Note: (Code Enforcement Officers estimate the cost to repair this structure is \$ \_\_\_\_\_ to \$ \_\_\_\_\_).