

Employee Injury Summary - 1st Quarter 2026

1/6/2026	Distribution	WATER SYSTEM WORKER II	Employee was using a hammer during job functions and struck his left thumb, breaking it.	hand	Yes
1/9/2026	Distribution	WATER SYSTEM WORKER II	Employee was using a chop saw to cut a pipe and got debris in his eye.	Eye	No
1/16/2026	Production	ELECTRICIAN	Employee was operating a gate and slipped on the ice and in the process cut his right ring finger.	Hand	No
1/22/2026	Business	Please Select Job Title	EMPLOYEE WAS WALKING NEXT TO A HOUSE AND SLIPPED ON ICE AND INJURED FINGER ON RIGHT HAND.	Hand	Yes
1/23/2026	Distribution	WATER UTILITY WORKER II	Employee cut right middle finger during operations.	Hand	No
1/23/2026	Distribution	HEAVY EQUIP OPERATOR-WATER	Employee slipped on ice while getting into TLB machine and strained his left shoulder.	Shoulder	No
1/28/2026	Distribution	WATER SYSTEM WORKER II	EMPLOYEE WAS IN THE PROCESS OF UNLOADING A TRAILER AND SMASHED HIS RIGHT HAND ON MATERIAL IN THE TRAILER.	Hand	No
1/29/2026	Distribution	WATER DISTRIBUTION SUPERVISOR III	EMPLOYEE WAS WALKING ON STREET BETWEEN WORK VEHICLES AND SLIPPED ON SOME BLACK ICE THAT THE EMPLOYEE DID NOT SEE. THE EMPLOYEE LANDED ON RIGHT KNEE AND STRAINED IT.	knee	No
1/27/2026	Production	WATER UTILITY WORKER I	EMPLOYEE WAS WORKING WITH A WOODCHIPPER AND THE EMPLOYEE WAS STRUCK BY A BRANCH ENTERING THE CHIPPER AND SPRAINED HIS RIGHT MIDDLE FINGER.	Hand	No
2/4/2026	Business	WATER UTILITY WORKER I	EMPLOYEE WAS GETTING OUT OF TRUCK AND SLIPPED ON ICE. THE EMPLOYEE PUT OUT HIS LEFT WRIST TO BREAK HIS FALL AND SPRAINED IT.	Hand	No
2/4/2026	Distribution	WATER SYSTEM WORKER II	EMPLOYEE WAS OPERATE A FROZEN GATE VALVE AND DURING THE PROCESS, THE EMPLOYEE WAS STRUCK BELOW THE EYE BY A GATE ROD HANDLE.	Head	No
2/10/2026	Production	MAITENANCE WORKER II	EMPLOYEE WAS LOOSENING A BOLT WITH A TOOL. DURING THE OPERATION, THE TOOL SLIPPED AND CAUSED A SHOULDER STRAIN.	Shoulder	No
2/11/2026	Production	WATER UTILITY WORKER I	EMPLOYEE WAS IN A PHYSICAL ALTERCATION WITH ANOTHER EMPLOYEE AND HE FELL ON HIS BACK INJURYING HIS TAILBONE, BACK, HEAD, AND NECK.	Back Area	No
2/13/2026	Select Division	WATER UTILITY WORKER II	EMPLOYEE WAS USING A GATE ROD TOOL AND DURING THE OPERATION IT BOUNCED BACK AND HIT THE EMPLOYEE AND CUTTING HIS FACE.	Head	No
2/19/2026	Distribution	WATER DISTRIBUTION SUPERVISOR II	EMPLOYEE WAS OPERATING A BLOW ROD AND DEBRIS FLEW INTO LEFT EYE.	Eye	No
2/27/2026	Production	PUMPING ENGINEER II	EMPLOYEE WAS WALKING AND SLIPPED ON ICE AND SCRAPPED RIGHT HAND.	Hand	No
3/3/2026	Production	WATER UTILITY WORKER I	EMPLOYEE GOT SAW DUST IN EYE CAUSING IRRITATION.	Eye	No
3/4/2026	Distribution	WATER UTILITY WORKER I	EMPLOYEE WAS GETTING OUT OF THEIR VEHICLE IN THE PARKING LOT AND SLIPPED IN ICE AND INJURED HIS RIGHT KNEE.	Knee	No
3/9/2026	Distribution	WATER SYSTEM WORKER II	EMPLOYEE WAS CUTTING A CAST IRON PIPE WITH A CHOP SAW AND GOT DEBRIS IN RIGHT EYE.	Eye	No
3/9/2026	Business	METER READER	EMPLOYEE WAS REPLACING WATER METER AND GOT DEBRIS IN LEFT EYE.	Eye	No
3/24/2026	Distribution	WATER DISTRIBUTION SUPERVISOR II	Employee was installing trench boxes and smacked right thumb between trench boxes.	Hand	No
4/15/2026	Engineering	WATER UTILITY TECHNICIAN II	employee was walking and rolled right ankle.	Ankle	No
4/20/2026	Engineering	PLUMBING INSPECTOR-RWS	Employee was putting on protective gear in close proximity to a fire hydrant and in the process struck his right knee into hydrant, causing a bruise to right knee.	Knee	No
4/21/2026	Distribution	WATER UTILITY WORKER I	EMPLOYEE WAS LOWERING BORE TOOL TO ANOTHER EMPLOYEE AND SMASHED FINGERS ON RIGHT HAND.	Hand	No
4/28/2026	Distribution	WATER UTILITY WORKER I	EMPLOYEE WAS CUTTING PIPE WITH A CHOP SAW AND GOT DEBRIS IN RIGHT EYE.	Right Eye	No
5/5/2026	Distribution	WATER UTILITY WORKER I	EMPLOYEE WAS WORKING ON A HYDRANT AND UTILIZING AN AIR TOOL. DURING THE OPERATION, DEBRIS GOT IN THE RIGHT EYEOF THE EMPLOYEE.	Right Eye	No
4/27/2026	Distribution	WATER UTILITY WORKER I	EMPLOYEE WAS CLIMBING ON A TRAILER IN THE RAIN AND SLIPPED AND STRAINED HIS RIGHT KNEE.	Knee	No
5/14/2026	Distribution	WATER UTILITY WORKER I	EMPLOYEE WAS IN BACK OF DUMP TRUCK LOWERING DOWN BUCKETS OF SAND TO OTHER EMPLOYEES AND STRAINED RIGHT SHOULDER.	Shoulder	No
5/30/2026	Administration	CUSTODIAN II	THE EMPLOYEE WAS WEARING OUR MASCOT SUIT AND IT IS NOT VERY ERGONOMIC. DURING THE ACTIVITY, THE EMPLOYEE INJURED HIS NECK AND RIGHT SHOULDER.	Neck and Shot	No
6/9/2026	Administration	CUSTODIAN II	EMPLOYEE WAS STRUCK FROM BEHIND DURING A MOTOR VEHICLE CRASH AND HAS STRAIN IN HIS NECK AND LEFT SHOULDER FROM THE CRASH	Neck and Shot	No
6/9/2026	Production	UTILITY TRAINEE	Employee was involved as a passenger in a motor vehicle collision and has a sore back as a result form the collision.	back	No
6/30/2026	Distribution	WATER UTILITY WORKER I	THE EMPLOYEE WAS WALKING NEXT TO A "DRILL" TRUCK AND STRUCK HIS HEAD ON THE DRILL HEAD STICKING OUT THE BACK OF THE TRUCK. THE EMPLOYEE RECIEVED A LARGE CUT OF HIS HEAD.	Head	Yes