

See reverse for Notice of Lien Rights and Additional Terms and Conditions

DUCT CLEANING RECEIPT



FURNACE & FIREPLACE CLEANING (612) 627-9038

3648 SNELLING AVENUE
MINNEAPOLIS MN 55406

Certified NADCA Cleaners &
Dryer Vent Exhaust Technicians

Minneapolis Licensed, Bonded,
Insurance & Nationally Certified

FURNACE AND CHIMNEY CLEANING

Type Of Fireplace: ☐ Pre-fab ☐ Masonry

Number of Fireplaces: ☐ 1 ☐ 2 ☐ 3 ☐ 4

Wood Stove: ☐ Insert ☐ Free Standing

Type of Furnace: ☐ Gas F/A ☐ Oil H/W

☐ Oil F/A ☐ Gravity

☐ Gas H/W ☐ Other

Not Applicable
Unsatisfactory
Satisfactory


SAFETY INSPECTION

FIREPLACE

- 1 Creosote Build-up
- 2 Firebox/Gate/Fire Brick
- 3 Damper/Smoke Shelf
- 4 Smoke Chamber
- 5 Screen or Glass Doors
- 6 Tools

CHIMNEY

- 7 Brickwork
- 8 Mortar
- 9 Flue Tiles
- 10 Flashing
- 11 Crown/Wash
- 12 Chimney Cover/Cap
- 13 Height



FURNACE & AIR DUCT REPORT

14 Multiple Furnaces	Yes	No	Flue
15 In Floor Ducts			Heat Exchangers
16 Humidifier			Burners

Customer Runbeck
Address 887 Charles ave
City St. Paul State MN Zip
Phone 414-312-3773
Delivery Date 10-25-24
Day Fri
Date When Sold
Sold by LME Delivered by Alex

DRYER VENT EVALUATION

Make of Dryer
Discharge: Rear or Side (circle one)
Type: Electric Natural Gas Propane (circle one)
Location Access
Type of Duct Work Diameter
Type of Connector Diameter
Location of Termination
Condition of Duct Work
Breaks Separations or Voids

DESCRIPTION	Qty	AMOUNT
1 <u>Air ducts</u>		
2		
3		
4		
5		

FURNACE TEST RESULTS

CO Test

DRYER VENT MAGNAHELIC PRESSURE TEST

Before Cleaning

After Cleaning *

Subtotal	<u>399</u>	<u>00</u>
Tax	<u>9878%</u>	
Total	<u>438</u>	<u>41</u>

Signature: Kyle Runbeck

NOTE: This sheet is the result of a visual inspection done at the time of cleaning. It is intended as a convenience to our customers, not as certification of fire worthiness or safety. Since conditions of use are beyond our control, we make no warranties of the safety or function of any appliance and none is to be implied.

Credit Card #: _____ Expiration Date: _____ 3/4 Digit Code: _____

Elofson Electric

2520 County Road H2
Mounds View, MN 55112
651-260-2487
elofsonm@aol.com

Contract

Bill To	Work Performed At
Kyle Runbeck 887 Charles Ave St Paul, MN 55104	

DATE	TERMS
10/25/2024	ON RECEIPT

PURCHASE ORDER

Description	DATE	QTY	UNIT PRICE	AMOUNT
Install Correct Breakers				\$2,000.00
Replace 23 receptacles with tamper resistant				\$600.00
Fix Grounding Conductor				\$100.00
Fix Bathroom GFCI Polarity				\$100.00
Fix Garage GFCI				\$120.00
Install 20amp circuit in the dining room				\$500.00
Permit				\$200.00
Install a hardwired smoke/co detector				\$180.00
Install a hallway light fixture with 3way switching				\$400.00
Install a 15amp circuit for new water heater				\$300.00

The estimated price is not to exceed \$4500 unless there is additional scope not laid out
Mike Elofson

Mike Elofson 10/25/2024
Kyle Runbeck 10/25/2024

Elofson Electric, Minnesota Electrical Contractor License Number EA720235	TOTAL	\$4,500.00
---	--------------	-------------------



KELLY PLUMBING & HEATING (KPH)

1932 St. Clair Ave, St. Paul, MN 55105
(651) 699-1232

office@kellyplumbinginc.com
<https://kellyplumbinginc.com>

PROPOSAL FOR HOMEOWNER

Date: September 27, 2024

Customer:	Project Location:
KYLE RUNBECK 414-312-3773 KYLE.RUNBECK@GMAIL.COM	887 CHARLES AVE ST PAUL, MN 55104

We hereby submit specifications and estimates for:

MISCELLANEOUS CODE VIOLATION REPAIRS

1 - Furnish & install a code compliant gas valve for the range and cap any piping as needed.	
2 - Furnish & install a code compliant gas valve for the dryer.	
3 - Furnish & install insulation on the dryer vent.	
4 - Furnish & install a 1" cold water main from the water meter to the tee that feeds the water heater. Replace the street side meter valve with a 1" code compliant shut-off valve.	
5 - Furnish & install a new laundry faucet for the cement sink. Replace the hot & cold bibs for the hook up of the washing machine.	
6 - Replace the kitchen sink drain piping with 2" code compliant piping. Replace from vertical 2" piping in the basement to the waste tee in the cabinet.	
7 - Cut out the tee feeding the abandoned humidifier valve.	
8 - Acquire city permits & coordinate city inspections.	
	\$4,295.00

APPROX COST: Four Thousand Two Hundred Ninety-Five Dollars and No Cents

Oct 28th
29th
Start Date

Initials KR