

Blue Sky Invoice

for
Carl Berger
1457 3rd St E
St Paul, MN 55106-5830
612-366-3734 Dale
jodisavasten@hotmail.com



6520 Edenvale Blvd, Suite 117
Eden Prairie, MN 55346-2564
(952) 944-1744

contact@blueskychimneyservices.com
www.mplsblueskychimneysweeps.com
Chimney Safety Institute of America Cert# 8045

Invoice No. 10378

Issued on Sat Jan 20, 2024

Inspection Summary Report

Fireplace

The liner system for the fireplace was found with violations of important codes and standards. The liner has gaps and voids preventing full and proper ventilation of the products of combustion (smoke, gas, creosote, fire, etc.)

The liner in the chimney has damage and does not fully contain the products of combustion. This violates fire code NFPA 211 14. 9. The fireplace should not be used until needed repairs are made per this code.

The firebox has heat damage to its back wall. Repair of back wall and fireback installation recommended.

Exterior Chimney

The chimney cement top is undersized and cracked and deteriorated and is allowing water/weather exposure causing brick and mortar damage and deterioration.

Chimney caps are also missing which will allow debris, rodents, birds, water to enter the chimney.

Optional Scope of Work

This estimate provides permanent seal off of fireplace.

CONTRACTOR AGREEMENT

Blue Sky Chimney Sweeps

IR712853

FEIN #46-2819804

This estimate and job deposit made constitutes a legally binding contract.

This estimate delineates the scope of the work and the location of the work and Blue Sky Chimney Sweeps shall furnish full scope of estimate.

20% Job Deposit. Balance due upon completion of work.

20 Jan 2024 Deposit Made. PAID IN FULL.

Full Fireplace Seal Off including chimney top seal off with top mounted damper/weather cap and fireplace opening seal off.

Name	Description	Amount
Fireplace Seal Off	Permanent Seal Off of Wood-Burning Fireplace Top Damper/Weather Cap Damper Control Arm Locked Installation Fireplace Opening Seal Off	\$1,750.00
	Tax	\$0.00
	Total	\$1,750.00
	Deposit Paid	\$390.00
	Balance Paid	\$1,360.00
	Amount Due	\$0.00

The chimney service inspection summary is a result of the visual inspection done at the chimney service date. It is intended as a convenience to our customer, not as a certification of fire worthiness or safety. No warranty is made regarding the safety or function of any appliance and none is to be implied. All chimney work includes warranty coverage. See separate warranty documentation. Warranty retention requires adherence to NFPA 211 codes and standards including annual inspection.

[QUESTIONS? CONTACT US](#)

contact@blueskychimneyservices.com
(952) 944-1744

Ask about our referral program!