

Mai Vang

From: Aaron Havlicek
Sent: Tuesday, January 23, 2024 7:01 AM
To: Dale Savasten
Cc: Clint Zane; Mai Vang; Joanna Zimny; J Savasten
Subject: RE: Chimney Sealed-1457 3rd Street

I received both emails containing the photos and documentation required. I will final/approve the mechanical code compliance.



SAINT PAUL
MINNESOTA

Aaron Havlicek
he/him/his
Mechanical Inspector
Department of Safety and Inspections
Suite 220
375 Jackson Street
Saint Paul, MN 55102
P: 651-266-9043
aaron.havlicek@ci.stpaul.mn.us



From: Dale Savasten <dale@savasten.com>
Sent: Monday, January 22, 2024 3:59 PM
To: Aaron Havlicek <Aaron.Havlicek@ci.stpaul.mn.us>
Cc: Clint Zane <Clint.Zane@ci.stpaul.mn.us>; Mai Vang <mai.vang@ci.stpaul.mn.us>; Joanna Zimny <joanna.zimny@ci.stpaul.mn.us>; J Savasten <jodisavasten@hotmail.com>
Subject: Re: Chimney Sealed-1457 3rd Street

Think Before You Click: This email originated outside our organization.

Hi Aaron,

Here are the pictures of the old vents blocked off, please let us know if there is any further information needed.

Thanks,

Dale Savasten









On Jan 22, 2024, at 3:21 PM, J Savasten <jodisavasten@hotmail.com> wrote:

Hello All,

Here is the paperwork and photos for the sealing of the chimney. Please let us know if you need more documentation.

Thank you!

**Warm Regards,
Jodi**

COMPASS-Edina

Jodi Savasten, Realtor

Office and Account Manager to Shelly Rae and Your Home by Design

5018 France Avenue South, Edina, MN 55424
612-306-1172

www.yourhomebydesign & www.compass.com

<image001.gif>

<CarlBerger_Invoice_10378.pdf>

<Fireplace Opening Seal Off.JPG>

<Top Damper Seals off Chimney at Top.JPG>

<Top Damper Control Arm.JPG>